

DPS6 Related Complaints
 ODI VOQ's and Ford TREAD-Reportable Reports
 data generated 12/2/13

Number of Reports by Source System and Safety Concern

Related (Multiple Items)

Count of ECI Record ID Safety Concern	Source System							Grand Total
	AWS	GCQIS Ford	MORS\ CUDL	FMC360	ODI	OGC	LMMS	
FATALITY Accident						1		1
Anxiety				1		1		2
Makes sick				1				1
Headache				1				1
Injury				4		1		5
accident w/ 2 inj					1			1
Accident w/ 1+ injuries				1				1
Accident w/ 1 inj						1		1
Accident w/ 1 inj and Fire						1		1
accident			6	3		32		41
almost accident					27			27
caused safety issue with traffic					1			1
Smoke U'hood	30	10	3	4				47
Sparks U'hood				1				1
Harness melted	2							2
Overheat	4							4
towed in	1				8			9
No 'Adverse' outcome	1	5	18	7	181	1	30	243
Grand Total	38	15	27	23	218	38	30	389

Memo: summary of allegations

Alleged fatality incidents 1
 Alleged injury incidents 13
 Alleged accident incidents 46
 Alleged TREAD fires 51

Memo: summary of fatality incident

OGC D082421
 '11 Fiesta
 incident May '13

Transmission stalled and caused an accident. Her son was going around a corner at 60 mph when it happened. The son died on impact. We requested additional information, but received no response.